

[/// bulges.keys.swims](http://bulges.keys.swims)

As can be seen in the pictures, the opposite bank is quite steep, and Walkers are sliding down the steep bank and landing on the bridge causing damage to the planking.

There are no Steps nor Handrail to slow the forward momentum, also the Stile at the top of the bank is missing one of the climbing boards making it difficult to get over.

Over seven metres this is a large task to repair. I can carry out temporary repairs to the Steps, Handrails and Stile as well as shoring up the Bridge, to keep the path open, but require some extra help to provide a more permanent fix.

